

■ **TC 1 S**







Digital meter for force and pressure measurement

**Characteristics**

- For force and pressure sensors
- Optional measuring adapter for measuring the crimping force of hydraulic crimping tools

Item	Part No.
Digital meter for force and pressure measurement	<b>TC1S</b>

Accessories	Part No.	Page
Charger 115V	TCC115	
Charger 230V	TCC230	

Measuring Adapter	Tool Series	Required sensor:	Part No.
	Series 50 EK 15/50, EK 15/50 G etc.	TF70	MA50
	Series 4 EK 35/4	TF70	MA4
	Series 18 HK 60/18, EK 18 PLUS etc.	TF70	MA18
	Series 22 HK 60/22, EK 22 PLUS etc.	TF70	MA22
	Quad-point indent crimping HK 60 VP, EK 60 VP/FT PLUS etc.	TF70	MAVP
	Series 13 HK 120/25, EK 120/42 etc.	TF130	MA120



■ **TF**

Force sensor for measuring the crimping force

**Characteristics**

- For connecting to TC 1 S with appropriate measuring adapter

Item	Part No.
Force sensor 70 kN	<b>TF70</b>
Force sensor 130 kN	<b>TF130</b>



■ **TP 1000**

Pressure sensor for measuring oil pressure to 1000 bar

**Characteristics**

- For connecting to TC 1 S

Item	Part No.
Pressure sensor 1000 bar	<b>TP1000</b>

